

State Route 138 (between Jct 18/138 and Crest Forest Drive) upper slope damage. Shows area of continuing slide on upper slope. (February 24, 2005)



State Route 138  
(between Jct 18/138 and Crest Forest Drive)  
upper slope damage. This crevice is over 100 feet wide  
located about 350 feet above SR-138  
(February 24, 2005)



State Route 138  
(between Jct 18/138 and Crest Forest Drive)  
upper slope damage. Shows depth of crevice  
- over four foot deep. (February 24, 2005)